

June 2023 River Fly Monitoring; clearing fallen willows and other debris from Letcombe Brook near Philberds Manor



July 2023 Draining Letcombe Brook to repair Dandridge Mill Sluice



July AGM 2023



August 2023 Letcombe Brook drained – upstream of Weir Farm; start of mill race; just upstream of the mill



September 2023 Michaelmas Fayre The Hanneys Flood Group; The Nigel Eady Community Woodland; Emergency Team Stand



October 2023 Floods – Botney Bridge;


The Iron Bridge



Brookside

Hall Flood Defences

Main Street



Halls Lane and Lower Mill



Main Street



November 2023 Flooding Halls Lane, Clearing grass cuttings from blocked grips




Lower Mill Bridge Upstream Downstream



Church Street



HWMH Flood Barriers



Lower Mill Cottage Sandbag Store



Headings Pond Gullies, Ditch and Culvert Clearing

Before



After



Before



After



Before



After



Summertown Waterlogged



Grip and gully clearing Summertown and Main Street



Lower Mill Bridge Sandbag Store



Road gully outlets leading directly into Halls Lane Non-return valves fitted July 2024



Blocked Gullies Grange Farm / Morlands



December 2023

More drain clearing in West Hanney



January 2024 – No Working Party but extensive flooding throughout the villages

EH Allotments



Footpath washed away



Philberds Cottage



Brookside



Morlands





Ashfields / Ebbs Lane



Iron Bridge




HWMH Car Park



Images of East and West Hanney



Tesco Abingdon





February 2024 More drain and gully clearing in West Hanney




March 2024 More drain and gully clearing in East Hanney



April 2024 Removing a fallen tree Charlotte's Bottom





Thank you to all those who have contributed photographs, coffee and cake.